## RECEIVED

217/786/6992

JAN 26 1978

E.P.A. \_D.E.P.C.

is Reply Refer To: Sangamon County - Land Pollution Control - Spfld./Buerkett #2 - #16782516

January 25, 1978

Mr. Merle Buerkett Rural Route #2, Koke Hill Road Springfield, Hillnois 62707

الحوارث الإ

Dear Mr. Buerkett:

Your solld waste disposal facility located on North Dirksen Parkway was inspected on December 13, 1977, by Gil Stauffer, representing this Agency.

it was observed during the inspection that a surfaced haul road extending westward from the central portion of the site to the adjoining property had been constructed utilizing demolition material as a road base. A request to this Agency to build this road was denied by letter on December 15, 1976. Appropriate Supplemental Permits must be obtained, therefore, to reflect such changes.

... Daily cover is not being provided adequately to all refuse. All solid waste received daily must be covered with a minimum of six (6) inches of compacted suitable natural earthen material by the end of that day's operation.

... Soild waste was being deposited at the top of the sippe in violation of Soild Waste Rule 303(a) which states that all waste shall be deposited into the toe of the fill or into the bottom



of the trench. This practice ensures better spreading and compaction density in the fill; reduces the total volume of cover material needed; and will reduce future settling problems.

It is suggested that you take immediate steps to resolve the conditions described above.

Sincerely.

Rone Van Someron, Central RegionaManager

Land Field Operations Section

Division of Land/Noise Pollution Control

RVS:dt

cc: Division File > Central Region

Land FOS Manager